## **ACCESSORIES FOR VACUUMS**

WSA 700P STS 130 STS 260 STS 260A STS 400 STS 750 STA 300

Accessories fo	r Vacuums		0) 0	0,	0, 0	, 0,	0,
•	Hepa Filter (Ref. No.: <b>617049</b> )				Π	Ī	
	Pre-filter (Ref. No.: <b>617021</b> )						
0	Pre-filter (Ref. No.: <b>617061</b> )						
	Pre-filter (Ref. No.: <b>617395</b> )						
7	Pre-filter (Ref. No.: <b>617218</b> )						
	Floor suction nozzle (Ref. No.: <b>617202</b> )						
	Floor suction nozzle (Ref. No.: <b>617206</b> )						
	Floor suction nozzle (Ref. No.: <b>617348</b> )						
//	Rubber blades (Ref. No.: 617203)						
//	Brush blades (Ref. No.: <b>617204</b> )						
	Dustbag (Ref. No.: <b>615240</b> )						
	Hose, antistatic (Ref. No.: <b>617199</b> ) Ø 38 mm, 5 m						
	Hose, antistatic (Ref. No.: <b>617208</b> ) Ø 50 mm, 5 m						
	Hose, antistatic (Ref. No.: <b>617212</b> ) Ø 50 mm, 10 m						
CONTROL OF THE PARTY OF THE PAR	Hose, antistatic (Ref. No.: <b>617213</b> ) Ø 70 mm, 5 m						
INFORMATION OF THE PARTY OF THE	Hose, antistatic (Ref. No.: <b>617214</b> ) Ø 70 mm, 10 m						
	Hose, antistatic (Ref. No.: <b>617215</b> ) Ø 50 mm, 2 m						

			W TS	TS TS	rs rs	ST
Accessories fo	r Vacuums					
- High	Hose, antistatic (Ref. No.: <b>617216</b> ) Ø 70 mm, 2 m					
	Hose (Ref. No.: <b>617345</b> ) 5 m					
	Kit CEE test plug (Ref. No.: <b>722199</b> )					
Adapters and	connections for the optimal connection bet	ween machine and vacuum cleaner				
	Quick coupling nozzle 60-50 (Ref. No.: <b>617070</b> )					
	Quick coupling nozzle 60-70 (Ref. No.: <b>617279</b> )					
	Adapter connection G38/38 (Ref. No.: 617198)					
	Adapter connection G38/50 (Ref. No.: 617054)					
	Adapter connection G50/50 (Ref. No.: 617207)					
	Adapter connection G70/70 (Ref. No.: 617268)					ı
	Adapter connection G50/76 (Ref. No.: <b>617267</b> )					
	Adapter connection G70/76 (Ref. No.: <b>617269</b> )					
	Hose connector G38/G38 (Ref. No.: 617272)					
	Hose connector G50/G50 (Ref. No.: <b>617270</b> )					
	Hose connector G70/G70 (Ref. No.: 617271)					
	Adapter connection 50/70 (Ref. No.: 617274)					
	Adapter connection 76/70 (Ref. No.: 617276)			9	5TS STS 40 75	

GX/Y G = thread, X = suction-pad connection, Y = machine connection



## **VACUUM-MACHINE COMBINATIONS**

		WSA 700P	STS 130	STS 260	STS 260A	STS 400	STS 750	STA 300	STA 550
Grinding and milling machines	Suction outlet					0,	0,		0,
DSM 250	Ø 50 mm								
DSM 400	Ø 50 mm								
DSM 450	Ø 50 mm								
DSM 530	Ø 50 mm								
DSM 530S	Ø 70 mm			X	X				
DSM 650S / RC	Ø 70 mm			X	X				
DSM 800S / RC	Ø 70 mm			X	X				
WDS 250	Ø 70 mm								
WDS 530	Ø 50 mm			X	X				
BEF 201 / V	Ø 50 mm								
BEF 204	Ø 70 mm								
BEF 250 / V	Ø 70 mm			X	X				
BEF 320 / V	Ø 70 mm			X	X				
BEF 400RC	Ø 70 mm								
recommended possible	possible only with adapter c	onne	ction	50/70	(Ref.I	No.: 6	 1727	4)	